

# Vivi Receiver Release 2.3.1 (Recommended)

## What's changed?

We've fixed an issue where URLs played through Video Direct from previous versions of the Vivi App (2.15.2 and below) would stop playing after a few seconds on Vivi Receivers running firmware 2.3.0.

## Who does this affect?

Vivi users on previous versions of the Vivi App who try to play URLs through Video Direct on Vivi Receivers running firmware 2.3.0.

## Who should update to this release?

It is recommended that all users upgrade to this version.

[Download Vivi Receiver Firmware 2.3.1](#)