

Vivi Receiver Release 2.3.3 / App Release 2.16.2 (Optional)

What's changed?

We have fixed video and audio synchronisation issues on Intel-based Chromebooks that occurred following the Chrome OS 72 update.

Who does this affect?

Vivi users with Intel-based Chromebooks running Chrome OS 72 and above.

Who should update to this release?

All Vivi users with Intel-based Chromebooks.

[Download Vivi Receiver Firmware 2.3.3](#)